


- | | |
|---------|-------------------------------------|
| VR277E: | VR277, VR1200 |
| VR277K: | VR22, VR269, VR277 |
| VR010P: | VR15P, VR16L5, VR17L |
| VR433: | VR261, VR263, VR440, VR442, 2xVR444 |
| NR.12: | VR2E, VR23, VR1201 |
| NR.12B: | VR2E, VR23, VR1201B |



VOLA A/S
 Lunavej 2
 DK-8700 Horsens
 Tlf : + 45 7023 5500
 Fax: + 45 7023 5511
 sales@vola.com
 www.vola.com

VOLA HV1E

Dato


Dec. 12

Rev.


4

Blad

SB21.10



- VR270A: VR266A, VR270A
 VR2609: 2xVR2605, VR2609
 VR2650: 2xVR41, VR2652, VR2629
 VR2651: 2xVR41, VR2652, VR2629 (USA)
 VR2654: ● 4xVR2647, VR2649, 2xVR2650, 2xVR266A
 VR2655: ● 4xVR2647, VR2648, 2xVR2650, 2xVR266A



VOLA A/S
 Lunavej 2
 DK-8700 Horsens
 Tlf : + 45 7023 5500
 Fax: + 45 7023 5511
 sales@vola.com
 www.vola.com

VOLA VR2618 HV1E/4100

Dato
Nov. 11

Rev.
2

Blad
SB21.16